

County: MONMOUTH
Municipality: SOUTH BELMAR BOROUGH

A SITES WITH ON-SITE SOURCE(S) OF CONTAMINATION

Site Name		Site Address	Site Identifier
Contact	Case Number	Case Status - Status Date	Control/Remedial Action Type
1900 MARGERUM AVE		1900 MARGERUM AVE	NJL800474041
BFO-S	990224163304	ACTIVE - 4/21/99	
712 TWENTY FIRST AVE		712 TWENTY FIRST AVE	NJL800405045
BFO-S	980511143148	ACTIVE - 6/10/98	

2 SITES WITH ON-SITE SOURCE(S) OF CONTAMINATION IN SOUTH BELMAR BOROUGH